


Unplanned Exposure During Diving in the Spent Fuel Pool

Andreas Ritter, KKL

Diving in the Spent Fuel Pool




Kernkraftwerk Leibstadt

August 31st 2010, during RFO26

- When a diver left the spent fuel pool, his electronic dosimeter was alarming. The display showed 40,1 mSv.
- The divers TLDs were immediately read out on site:


- ✧ Whole body: 19 mSv
- ✧ Right finger: 1123 mSv
- ✧ Left hand: 306 mSv
- ✧ Left foot: 11 mSv



- The dose limit for hands (500 mSv/a) was exceeded
- The situation concerning the whole body (dose limit: 20 mSv/a) was questionable (2 different readings, TLD and EPD)

The Job


- The Inclined Fuel Transfer System (IFTS) moves fuel and reactor internals from the Reactor Building to the Fuel Building and vice versa
- Planned maintenance: Replacement of cables on IFTS
- The same job has been performed safely by a diver in the past
- Decided to do it with the diver again



The Layout


- Spent Fuel Pool „East“
- Wall
- Gate
- Transfer Pool
- Gate
- Wall
- Spent Fuel Pool „West“

IFTS Tube



The Survey (before start of cable exchange)

- Dose rate survey with submerged probe performed by diver at place of work (locations 1 – 6)
- Reading outside water at RP post
- Reading at locations 1 – 6 within expectations: no danger



DL-Messungen Transfer PX50 / ZD1 BE-Lager:

Messung mit: Mitteldosissonde „Thermo FH40G-X“

Serie-Nr.: 10836-001


Datum	Messpunkt	DL _{Kontakt} (mSv/h)	DL _{Abstand 50 cm} (mSv/h)	Bemerkung
26.08.2010	1	2.0	0.055	
	2	3.2	0.030	
	3	0.7	0.120	
	4	1.5	0.020	
	5	Keine Messung		Kein vorgesehener Arbeitsbereich
	6	13.0	0.030	
30.08.2010	1	DI-Messungen im Arbeitsbereich seitlich vom Rohr: 0.3 bis 0.6 mSv/h		
	2			
	3			
	4			
	5	Keine Messung		
	6	Keine Messung		

The Briefing

- The fuel pool gates were left open to allow cool water to flow in (heat stress protection for the diver)
- The diver was briefed not to pass the gates because of spent fuel on the other side: high risk
- The diver was **not** briefed not to touch anything unidentified
- The diver was **not** briefed to strictly stay inside the surveyed area of the transfer pool
- The diver was briefed for requirements specific to diving (air supply, communication rules etc.)


What happened?

- The diver spotted an unidentified object during an interruption of the task
- Asked the diving supervisor what to do
- Was told to put it in his tool basket
- While lifting of the basket the Area Radiation Monitor alarmed, with the basket still submerged. Teletector reading at pool railing was elevated
- Basket lowered again
- Diver leaves pool




The Object

- Dose rate reading in excess of 100 Sv/h (10'000 R/h) contact
- Identified as top part of Dry Tube (= housing of neutron monitors in the reactor core). Highly activated by neutron flux
- Found in a remote part of pool
- Not accessible to submerged probe from outside pool due to geometry



The Shielding

- Water shielding is very effective
- No dose rate in a distance > 1.4 meters of drytube
- Source is hard to localize by dose rate surveys
- Extremely high dose rates if source is brought close to parts of body
- Dose rate change is very fast




The Diver

- Had no signs of acute radiation syndrome
- Was put under medical examination
- Was closed out from radiation work
- Was offered psychological assistance
- Had a personal talk with the plant manager, who expressed his regrets for the incident
- Received radiation-biological basics by senior expert of regulator
- Should not expect any longtime consequences

How did the Drytube get there?

- Drytubes were removed and cut in pieces in the reactor cavity during RFO2006
- Some pieces were slightly longer than drytube insert for IFTS
- During tilting operation of the IFTS cask, the top part of a drytube was probably sheared off
- Drytube top part was on bottom of spent fuel pool since 2006



Shortcomings

- The loss of highly radioactive material was not noticed
- The missing part of the drytube was not detected
- The EPD alarm was not heard because of air bubble noise
- There was no remote radiation survey during diving
- There was no written order (to remove the drytube),
- therefore RP was not involved in the drytube removal
- The hazard of foreign material was not assessed
- The procedure for maintenance tasks generally requires clean up of the work area

Corrective action as of end december 2010

- **Drytubes will be moved in a closed container (done)**
- **A procedure for collection of loose material in pools shall be put in place (was missing before)**
- **The audible alarm of the divers EPD will be brought on his headset**
- **Teledosimetry will be installed on the divers body**
- **A procedure to track the loss of hazardous material shall be developed**
- **Pre-job-briefing improvements**


The regulators findings

The regulator assessed by calculations

- ✧ the whole body dose: 28 mSv (2.8 rem)
- ✧ the hand dose: 7500 mSv (750 rem)
- **The event was rated INES 2 „exposure of a worker in excess of the statutory annual limits“**
- **The issue will not be dealt with a court of law**
- **The drytubes activity was assessed to be 1.8 TBq (50 Ci)**
- **The divers video monitor must be observed by an RP Tech**
- **Unknown objects to be handled only with a tool**
- **Dose rate survey in an extended area also by handheld submersible instrument**

Side effect: the broken TLD

- The divers TLD at the finger was broken due to mechanical loads during use
- The broken TLD was repaired with instant glue and processed „normally“
- This process was validated:



Questions?

