#### DC Cook Baffle Bolt Inspection and Repair







ISOE Joint Session on NPP Aging ALARA Planning

David W. Miller

DC Cook Radiation Protection Department

American Electric Power

November 8, 2017



#### **Preparations**

Special thanks to the RP staff at Indian Point and Salem for allowing Cook NATC to benchmark and learn from their baffle bolt replacement experience.







## Scope of Issue


- Baffle bolt degradation was found at the Indian Point and Salem Plants in March and April 2016
- Industry response guidance, endorsed by the US Nuclear Regulatory Commision, issued in 2016 by Westinghouse Reactor Services Group
- Both units of Cook Units 1,2, along with Indian Point 2&3, Salem 1,2, and Diablo Canyon 1 fall into the most urgent category of response
- Cook's current strategy is to replace at least 200 bolts during each of the next two refueling outages on each unit. Total population per reactor is about 800 baffle bolts.







### So, What's a Baffle Bolt?










# How to put a Square Peg in a Round Hole










## Bird's Eye View of Set Up










# Männer bei der Arbeit (Men at Work)









## **Tool Head Repair Area**










# Overhead View of Tool Head Repair Area









## **Tool Repair**









## **The Usual Suspects**





MILLING OF FOUR (4) GROOVES







### **FME Controls**










# **View Looking South**










# RP Technician Engagement/Innovation









#### **Overall Performance**

- 100 percent ECT inspection, 201 bolts replaced
- 12.7 rem vs. 15 rem goal
- One PCE > Level 1
- Zero dose/dose rate alarms
- Extensive planning (to the extent practical)
- Rigorous tool handling/removal process
- JIT training developed (by RPT) and delivered to all personnel supporting baffle bolts







### Cook ALARA Experience, con't.

- Solid ALARA plan with clear hold points and stop work criteria
- Five bolts shipped to off-site vendor for failure analysis
- Pre-job meeting with vendor to understand potential cultural differences (German vs US NPP work behaviors)
- Shiftly pre-job briefs/vendor engagement/teamwork
- Dedicated RP support, strong AEP ownership, strong technician ownership and engagement







#### **Lessons Learned**

- Receipt of material anticipate potentially higher dose rates and contamination levels
- Additional cavity cleanup through SFP demin not necessary
- Ensure accountability for tethered tools
- Monitor downdraft table and ultrasonic sink to maintain dose rates low
- Complete overhaul of FS 3 tool was very beneficial







#### **ALARA Lessons Learned**

- Demobilization plan needs to be thorough and must be adhered to
- If EDM (bolt vaporization) is necessary, ensure capture of all debris and anticipate much higher dose rates on vacuum hoses during demobilization (2010 40 R/hr vs. 2016 200-400 mR/hr)
- Utilize a "tool pool" to hydrolaze tools underwater in parallel with other activities
- Lifting hook bent when demobilizing core plate FME cover







#### **Current Status of Cook Unit1**

- Unit 1 outage commenced on September 13, 2017
- 95 days planned to accommodate baffle bolt replacement
- 48 batches of baffle bolts to be completed by Westinghouse Services Group
- Westinghouse specialized tooling is key to the projects success
- 100 Cook baffle bolts have been replaced as of November 3
- Expect to be completed in early December







#### **ISOE** Initiatives

- Conference Calls monthly on plant life extension and new technology ALARA information exchange
- US HPs are reviewing NATC suggested standardized RWP job titles and subtasks titles for baffle bolts (8<sup>th</sup> RWP category being standardized)
- Allows better comparison of RWP job dose, manhours, crew size and pre-job ALARA briefings effectiveness
- Goal is to not repeat ALARA lessons learned at another site or another baffle bolt episode at the same site
- Cook 1,2 plant life extension program is funded at \$1 billion dollars over a 5 7 year period including Radiation Monitoring System completed replacement with French manufactured system.







## Thank You

Merci!

Questions?



