

# Observations and Findings in the Area of ALARA

2009 ISOE North American ALARA Symposium / EPRI Radiation Protection Conference Fort Lauderdale, Florida
January 13, 2009

Steve Garry, CHP
US NRC Headquarters
Division of Inspection and Regional Support
301-415-2766; smg2@nrc.gov



### **Purpose**


Highlight current ALARA Performance

 Discuss NRC ALARA inspection findings and observations over the past 3 years


Discuss Areas for Focus and Opportunity.



#### **Average Annual Collective Dose**











#### Average Annual Number of Workers with Measurable Dose













Number of Reactors

#### Number of Operating Reactors











- 2006 4 Green Findings, 2 Non-cited Violations
- 2007 8 Green Findings
- 2008 4 Green Findings (through Sept 30<sup>th</sup>)



- Work not adequately planned and executed for purposes of exposure reduction (four examples- refueling, pump work, vessel head work, corrosion control)
- Work not properly planned in the area of person-hours for sump modification
- Work planning issues for insulation work caused worker inefficiency and additional dose



- Work not effectively controlled or planned for refuel floor work, person- hours exceeded planned estimates
- Violation Failure to use engineering controls for steam generator work caused unplanned dose
- Violation Failure to use engineering controls for reactor cavity work caused unplanned dose



- Re-work caused increased work hours and dose.
- Inexperienced workforce caused significant increased work hours and dose.
- Inexperienced work force using poor ALARA practices, and extensive rework resulted in additional dose.



- Failure to provide detailed work package instructions to isolate transmitter before opening drain valve, causing unplanned and unintended exposure
- ALARA work planning was less than adequate resulting in rework, and dose > 5 rem and > 50% criteria
- Rework caused by planning errors and craft errors resulted in dose > 5 rem and > 50% criteria
- 3 different work activities resulted in > 150% of original planned dose



- Failure to effectively implement radiological and engineering controls (organizational and programmatic deficiencies) resulted in > 5 rem and > 50% criteria
- Failure to manage source term and work activities resulted in > 5 rem and > 50% criteria
- 20.1501 survey requirements were not met in that respirators were issued without an evaluation for the need for respirators
- Failure to implement dose controls by ineffective ALARA planning and controls



# **Areas of Focus/Opportunities**

- Use best pre-job assumptions for ALARA analysis (work scope, person-hours, radiation dose rates)
- Consider experience levels, provide additional Supervision/oversight when less experienced crews
- Oversight Validate ALARA planning assumptions early in work activity (dose rates, hours, shielding)
- Track on-going job performance, re-evaluate, revise dose estimates
- Off-track dose estimates Modify analysis, re-establish ALARA actions, re-approve ALARA goals



# **Areas of Focus/Opportunities**

- Rework Re-evaluate, verify or modify ALARA planning and document your evaluation
- Expanded work or rework Recognize, acknowledge and document why work was expanded or rework was needed
- Mistakes Do stand-downs, discuss and correct mistakes with crews, and document immediately in corrective action programs
- Do apparent cause analysis and find the real problems



### **Areas of Focus/Opportunities**

- Long term ALARA planning
  - Chemical controls
  - fuel cleaning
  - Partial system chemical decon
  - High Pressure decontamination of hot spots
  - Component replacement